

Figure 1



Pore size distribution plat

D-H method (Fram adsorption branch)

Figure 2



Pore size distribution plot

D-H estand (From adsorption branch)

Figure 3

